

CONTENTS

Chapter No.	Section	Title	Page No.
1.		Introduction	1 – 3
	1.1	General	1
	1.2	Objectives of Material Survey	1
	1.3	Construction Materials	1
	1.4	Layout of the Report	2
2.		Natural Construction Materials	4 – 22
	2.1	Introduction	4
	2.2	Review of Available Information/ Data/ Reports	4
	2.3	Locally Available Materials	4
	2.3.1	Borrow Material	5
	2.3.2	Quarry Material: Coarse Aggregates and Stones	7
	2.3.3	Fine Aggregates	11
	2.3.4	Water for Construction	14
3.		Processed Construction Materials	23 – 26
	3.1	General	23
	3.2	Processed Construction Material	23
	3.2.1	Cement	23
	3.2.2	Reinforcement Steel	24
	3.2.3	Bituminous Binder	25
4.		Assessment of Subgrade Soil	27- 34
	4.1	General	27
	4.2	General Characteristics of Black Cotton Soil	27
	4.3	Constructional Problems in Black Cotton Soils	27
	4.4	Subgrade Soils in Use	28
	4.5	Pragmatic Constructional Approaches in Expansive Soils	28
	4.6	Presence of Other Problematic Soils at the Nanded Project Area	30

Chapter No.	Section	Title	Page No.
5.		Environmental Concerns	35
	5.1	Environmental Hazards and Mitigation Measures	35
6.		Conclusions	36
	6.1	Concluding Remarks	36
		Annexure - <i>Laboratory Test Results on Construction Materials</i>	37 – 56

LIST OF TABLES

Table No.	Title	Page No.
1.1	Construction Materials	2
2.1	Desired Borrow Material (Murrum) Characteristics	6
2.2	Borrow Material Properties of Jhari and Shikhachiwadi Quarry	7
2.3	Properties of Basalts Available in India (IRC:SP:20-2002)	7
2.4	Observed Quality of Quarry Materials	9
2.5	Desired Properties of Quarry Materials	10
2.6	Sand Sources in Nanded City	11
2.7	Fine Aggregates: Desired Properties	12
2.8	Gradation Requirements of Sand/ Fine Aggregates (IS 383)	13
2.9	Properties of Sand Deposits at Vaasri & Nagapur	13
2.10	Desired Water Quality	15
3.1	Types of Cement (IRC:21 – 2000)	23
3.2	Bulk Source of Cement in Nanded	24
3.3	Quality of Steel	25
3.4	Physical Properties of Bitumen (IS 73 – 1961)	25
4.1	Generalized Properties of Subgrade Soils in Nanded Region	28
4.2	Test Results on Subgrade Material from selected Roads	31

LIST OF FIGURES

Figure No.	Title	Page No.
2.1	Quarry Sources at Jhari, Musalmaanwadi & Shikaraghat (Source: NWCMC, Nanded)	16
2.2	Metal & Murum Source at Nanded-Mudkhed Road	17
2.3	Metal & Murum Source at Nanded-Mudkhed Road	28
2.4	Quarry Material at Nanded-Osmannagar Road	19
2.5	Quarry Material at Nanded Osmannagar Road (SH224)	20
2.6	Quarry Material at Ardhapur-Tamsa-Aashti (SH220)	21
2.7	Quarry Material at Nanded-Osmannagar road (SH224)	27

LIST OF PLATES

Plate No.	Title	Page No.
2.1	Murum Quarry at Jhari	5
2.2	A Close View of Jhari Murum Quarry	5
2.3	Stone Quarrying at Jhari	8
2.4	Sorting & Loading of Stones at Jhari Stone Quarry	8
2.5	Stone Quarry at Musalmaanwadi	8
2.6	Private Stone Crusher at Jhari Area	8
2.7	Abandoned Stone Quarry at Musalmaanwadi Which can be Revived by Acquiring Adjacent Land	9
2.8	Sand Deposit at Vaasri Area	11
2.9	Excavation & Loading of Sand at Vaasri in Progress	11
2.10	Sand Loading at Nagapur – Note a Gurudwara at the Background	12
2.11	Stacking of Sand to meet Requirements During Monsoons	12
2.12	Godavari River – A Perennial Source of Water	14
4.1	Deep Seated Black Cotton Soil is Common Feature in Nanded	28
4.2	Open Field of Black Cotton Soil at Nanded	28